



## HAYDEN PAVING, INC.

4710 Windsong Trail, Houston, TX 77084 O: 281-855-7710 F: 281-856-2506

### Quotation

Quote Number: 29175

Quote Date: 3/16/2021

Quoted By: Michael Henry

#### Quoted to:

City of Shoreacres  
601 Shoreacres Blvd.  
La Porte TX 77571

Job Name: City of Shoreacres Fairfield Ave  
Fairfield Ave.

Shoreacres TX 77571

Phone: 0

Contact	Good Through	Payment Terms	Job Location
0	4/15/2021	Net 30 Days	0
Item	Description	Amount	
Supply material, labor and equipment to perform the following:			
1A	FAIRFIELD (BROADWAY TO SUNRISE) ASPHALT MILL AND OVERLAY: Mill 2" of the existing drive lane and haul off. Apply SS-1 tack coat @ 0.05 to 0.15 gal./sq., place and compact 2" of type 'D' HMAC on existing asphalt pavement. Area totaling approximately 37,800 sq.ft.	\$54,810.00	
1B	FAIRFIELD (BROADWAY TO SUNRISE) BASE REPAIRS: Remove 8" of the existing deteriorated base and haul off. Place and compact 8" of black base asphalt. Area totaling approximately 746 Tons. This estimate is based off of a visual inspection of the road. More or less may be necessary to properly repair the road. The price per ton is \$111.22.	\$82,970.12	
2A	FAIRFIELD (SUNRISE TO MIRAMAR) ASPHALT MILL AND OVERLAY: Mill 2" of the existing drive lane and haul off. Apply SS-1 tack coat @ 0.05 to 0.15 gal./sq., place and compact 2" of type 'D' HMAC on existing asphalt pavement. Area totaling approximately 23,100 sq.ft.	\$33,495.00	
2B	FAIRFIELD (SUNRISE TO MIRAMAR) BASE REPAIRS: Remove 8" of the existing deteriorated base and haul off. Place and compact 8" of black base asphalt. Area totaling approximately 171 Tons. This estimate is based off of a visual inspection of the road. More or less may be necessary to properly repair the road. The price per ton is \$111.22.	\$19,018.62	
Base		\$190,294	
Bond Cost		\$2,674	
Subtotal		\$192,968	
Exempt - contingent upon receipt of Tax Certificate 8.25%		\$0	
Total		\$192,968	

Notes	
1	This quote does not include the cost of permits, which may or may not be required, or the plan work necessary to obtain such permits.
2	Price is subject to change due to any freight increases, liquid asphalt increases, and fuel surcharges incurred.
3	Hayden Paving shall not warranty asphalt failures caused by sub-grade or base failures where asphalt is placed on existing sub-grade, base or asphalt surface which was not installed by Hayden Paving.



## HAYDEN PAVING, INC.

4710 Windsong Trail, Houston, TX 77084 O: 281-855-7710 F: 281-856-2506

- |   |   |
|---|---|
| 4 | Asphalt paving industry recommended grade for proper drainage of asphalt surfaces is 2%. Designed grades of less than 1.5% will increase the chances of water ponding. Hayden Paving shall not guarantee zero ponding on surfaces designed with less than 1.5% grade. |
| 5 | Engineering layout, offset stakes and string line elevation control costs are not included in this quotation. This quote is based upon the assumption that elevations shall be controlled by existing curbs, gutters, base material, etc                              |

### *"20 Years Experience"*

**Acceptance of proposal - The above prices, specifications and conditions are satisfactory and are hereby accepted. Hayden Paving, Inc is authorized to do the work as specified. Payment will be made as described by payment terms listed above. Hayden Paving, Inc. reserves the right to repossess any material that is not paid in full within 90 days of the job completion.**

Signature \_\_\_\_\_

Date \_\_\_\_\_

Print Name \_\_\_\_\_